

INSPECTION REPORT



End of contract

GENERAL INFO

File	315428
License plate	JK2025
Vehicle identification number	VXKUSHPY1RW075013
Dossier	2024263007
Make	Opel Mokka 1.2T 136 AT Edition
Mileage	30002
First registration	22/04/2025
client availability date	15/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
67	Wing Front Left / Trim / Replace	N
133	Bumper Rear // Painting	Y
157	Rear Bonnet / Trim / Replace	Y
213	Door Front Right // Painting	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures





Interior Cleaning // Small-stain



Bumper Rear // Painting-scratch



Rear Bonnet / Trim / Replace-scratch



Door Front Right // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Painting-scratch