

INSPECTION REPORT



End of contract

GENERAL INFO

File	318954
License plate	2CDA358
Vehicle identification number	TMBJP7NXXNY102803
Dossier	2021 139 149
Make	Skoda Oct.Com.1.0 eTec 81kW Cl
Mileage	153049
First registration	09/06/2022
client availability date	03/08/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
66	Wing Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
226	Side View Mirror Right / Shell / Replace Painted	N
233	Wing Front right // Painting	N
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Polish-scratch



Wing Front Left // Polish-scratch




Bumper Front // Smart Repair Medium-scratch



Wing Front right // Painting-scratch




Door Rear Right // Polish-scratch




Rocker Panel Left // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch




Wing Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Side View Mirror Right / Shell / Replace Painted-cracked



Interior Cleaning // Small-stain