

INSPECTION REPORT

End of contract

GENERAL INFO

File	321258
License plate	2BAY445
Vehicle identification number	TMAJD811BMJ051429
Dossier	2021 089 001
Make	Hyundai Tuc.T-GDi Hyb.169kW Fe
Mileage	128209
First registration	14/09/2021
client availability date	20/09/2026
inspectionDate	25/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
223	Side View Mirror Right // Replace Not Painted	Y
310	Wheel Two Tone Front Left // Repair	Y


Damage Pictures



Door Rear Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Right // Replace Not Painted-scratch





Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent