

INSPECTION REPORT



End of contract


GENERAL INFO

File	321095
License plate	PW7895
Vehicle identification number	TMBLN9NS1M8036400
Dossier	2020344001
Make	Skoda Kodiaq TDI200 Style 4x4
Mileage	199546
First registration	02/02/2021
client availability date	28/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
41	Windshield // Replace	N
103	Door Rear Left // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Left // Painting-scratch



Windshield // Replace-glass damage



Lettering Removal 15min-