

INSPECTION REPORT



End of contract

GENERAL INFO

File	313704
License plate	2BNK650
Vehicle identification number	W0VZT6EN3M1033389
Dossier	2021241003
Make	Opel Insignia 1.5D 90 Bus.Ed.
Mileage	105511
First registration	25/01/2022
client availability date	26/05/2026
inspectionDate	08/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
84	Door Front Left // Repair & Painting	N
93	Rocker Panel Left // Repair & Painting	N
104	Door Rear Left // Repair & Painting	N
14	Bumper Front // Repair & Painting	N
28	Front / Calendar / Replace	Y
32	Front Bonnet // Painting	N
63	Wing Front Left // Painting	N
72	Side View Mirror Left // Painting	N
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
150	Rear Bonnet // Smart Repair Small	N
162	Roof // Painting	N
174	Light / Rear Right / Replace	N
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
211	Door Front Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	N
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
851	Registration Card loss Arval name //	N



Damage Pictures




Bumper Front // Repair & Painting-scratch + dent



Front Bonnet // Painting-bad repair



Door Rear Right // Painting-bad repair



Bumper Rear // Painting-bad repair



Wing Front Left // Painting-bad repair



Dashboard / Steering Wheel / Replace-worn



Wheel Alloy Front Left // Repair-scratch




Wheel Alloy Rear Left // Repair-scratch



Roof // Painting-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch



Front / Calendar / Replace-scratch



Side View Mirror Left // Painting-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Front Left Door Interior Coating // Replace Completely-scratch



Wing Rear Left // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent




Rear Bonnet // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Repair & Painting-scratch + dent