

INSPECTION REPORT


End of contract


GENERAL INFO

File	308388
License plate	GG7996
Vehicle identification number	W1KEG1BB2PF036498
Dossier	2023206033
Make	Mercedes EQE 300 292 Business
Mileage	21462
First registration	02/08/2023
client availability date	18/03/2026
inspectionDate	19/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
158	Rear Bonnet / 3rd Stoplight / Replace	Y

Damage Pictures



Damage within Renta-norm-scratch



Wing Rear Left // Repair & Painting-dent



Light / Rear left / Replace-N comf / out of order



Rear Bonnet / 3rd Stoplight / Replace-scratch