

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                            |
|-------------------------------|----------------------------|
| File                          | 319904                     |
| License plate                 | DU4219                     |
| Vehicle identification number | YV1XZK7V3P2913703          |
| Dossier                       | 2022242001                 |
| Make                          | Volvo XC40 B3 163 Core Aut |
| Mileage                       | 49853                      |
| First registration            | 09/09/2022                 |
| client availability date      | 10/08/2026                 |
| inspectionDate                | 12/08/2026                 |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | N       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | N       |        |
| Registration certificate  |        | N       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | Y       |        |





## DAMAGES

| Damages | Type                                                  | Acceptable |
|---------|-------------------------------------------------------|------------|
| 13      | Bumper Front // Painting                              | Y          |
| 19      | Bumper Front / Lower Cover Not Painted / Replace      | Y          |
| 31      | Front Bonnet // Smart Repair Small                    | Y          |
| 83      | Door Front Left // Painting                           | N          |
| 110     | Wing Rear Left // Smart Repair Small                  | Y          |
| 133     | Bumper Rear // Painting                               | Y          |
| 156     | Rear Bonnet // Polish                                 | Y          |
| 196     | Door Rear Right // Polish                             | Y          |
| 214     | Door Front Right // Repair & Painting                 | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace | Y          |

## Damage Pictures



Door Front Left // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left // Smart Repair Small-dent



Front Bonnet // Smart Repair Small-dent



Door Front Right // Repair & Painting-scratch + dent



Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch



Door Rear Right // Polish-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Painting-scratch