

INSPECTION REPORT

End of contract

GENERAL INFO

File	321676
License plate	2BDT321
Vehicle identification number	W1K2050531R632281
Dossier	2021 250 064
Make	Mercedes C 300 E Sport Edition
Mileage	176866
First registration	14/10/2021
client availability date	07/09/2026
inspectionDate	14/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
228	Side View Mirror Right / Direction Indicator / Replace	N
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch



Rocker Panel Right // Smart Repair Medium-dent



Side View Mirror Right / Direction Indicator / Replace-cracked