

INSPECTION REPORT

End of contract

GENERAL INFO

File	320748
License plate	2DCL129
Vehicle identification number	VR3FCYHZTNY655696
Dossier	2022 241 148
Make	Peugeot 508SW 1.5 BHDi GT Pack
Mileage	184949
First registration	02/02/2023
client availability date	24/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
113	Wing Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	N
162	Roof // Painting	Y
194	Door Rear Right // Repair & Painting	N
231	Wing Front right // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
611	Front Left Door Interior Coating // Repair	N

Damage Pictures



Interior // Repair 1-scratch



Roof // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Left / Bottom Coating / Replace-scratch





Front Left Door Interior Coating // Repair-scratch



Door Rear Left // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent