

INSPECTION REPORT


End of contract

GENERAL INFO

File	321094
License plate	MY1307
Vehicle identification number	VR3USHNSSPJ730898
Dossier	2023055020
Make	Peugeot 2008 1.2 PT130 Allure
Mileage	75358
First registration	31/07/2023
client availability date	28/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
84	Door Front Left // Repair & Painting	N
104	Door Rear Left // Repair & Painting	Y
116	Wing Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
234	Wing Front right // Repair & Painting	Y
282	Bumper Rear / Trim Center / Replace	Y
330	Wheel Two Tone Rear Right // Repair	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Rear Bonnet // Polish-scratch



Bumper Rear / Trim Center / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch




Front Bonnet // Polish-scratch



Bumper Front // Polish-scratch




Wing Rear Left // Polish-scratch



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent




Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent




Wing Front right // Repair & Painting-scratch + dent





Door Front Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Side View Mirror Right / Direction Indicator / Replace-cracked



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



