

INSPECTION REPORT

End of contract

GENERAL INFO

File	313740
License plate	XY4771
Vehicle identification number	VR3USHNSSNJ662372
Dossier	2021342031
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	51063
First registration	26/07/2022
client availability date	26/05/2026
inspectionDate	29/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	







DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
131	Bumper Rear // Smart Repair Medium	N

Damage Pictures



Door Front Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Rear // Smart Repair Medium-scratch