

INSPECTION REPORT


End of contract

GENERAL INFO

File	307336
License plate	2FSC837
Vehicle identification number	VR3FRHNS2RY549088
Dossier	2023356412
Make	Peugeot 308 SW 1.2 130 Active
Mileage	35692
First registration	31/07/2024
client availability date	04/03/2026
inspectionDate	12/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
225	Side View Mirror Right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Damage within Renta-norm-scratch



Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch + dent



Interior Cleaning // Small-stain