

INSPECTION REPORT


End of contract

GENERAL INFO

File	320758
License plate	2BQX102
Vehicle identification number	W1K1183101N286064
Dossier	2021120063
Make	Mercedes CLA 180 d Business So
Mileage	81181
First registration	18/02/2022
client availability date	28/08/2026
inspectionDate	09/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
18	Bumper Front / Spoiler / Replace	Y
31	Front Bonnet // Smart Repair Small	N
81	Door Front Left // Smart Repair Medium	Y
110	Wing Rear Left // Smart Repair Small	Y
132	Bumper Rear // Smart Repair Large	N
139	Bumper Rear / Spoiler / Replace	N
144	Back Side // Polish	Y
210	Door Front Right // Smart Repair Small	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Smart Repair Large-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Back Side // Polish-scratch



Wing Rear Left // Smart Repair Small-dent



Door Front Left // Smart Repair Medium-dent



Front Bonnet // Smart Repair Small-scratch + dent



Bumper Rear / Spoiler / Replace-cracked



Bumper Front // Smart Repair Large-scratch



Bumper Front / Spoiler / Replace-scratch