

# INSPECTION REPORT




**End of contract**

## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 314426                        |
| License plate                 | 2AAK912                       |
| Vehicle identification number | W0VEFYHYCLJ898420             |
| Dossier                       | 2020184100                    |
| Make                          | Opel Comb.1.5D 75kW 2.3T L2H1 |
| Mileage                       | 129435                        |
| First registration            | 01/04/2021                    |
| client availability date      | 03/06/2026                    |
| inspectionDate                | 10/06/2026                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | Y       |        |
| Towbar (+keys)            |        | Y       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | N       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |






## DAMAGES

| Damages | Type                                                | Acceptable |
|---------|-----------------------------------------------------|------------|
| 13      | Bumper Front // Painting                            | N          |
| 272     | Bumper Front / Trim Right / Replace                 | N          |
| 275     | Bumper Front / Grid Right / Replace                 | N          |
| 114     | Wing Rear Left // Repair & Painting                 | Y          |
| 124     | Light / Rear left / Replace                         | Y          |
| 19      | Bumper Front / Lower Cover Not Painted / Replace    | Y          |
| 35      | Front Bonnet // Polish                              | Y          |
| 41      | Windshield // Replace                               | Y          |
| 54      | Headlight / Front left / Replace                    | Y          |
| 77      | Side View Mirror Left / Shell / Replace Not Painted | Y          |
| 106     | Door Rear Left // Polish                            | Y          |
| 109     | Door Rear Left / Window / Replace                   | Y          |
| 138     | Bumper Rear / Lower Cover Not Painted / Replace     | Y          |
| 159     | Rear Bonnet / Rear Window / Replace                 | Y          |
| 165     | Roof // Polish                                      | Y          |
| 184     | Wing Rear Right // Repair & Painting                | Y          |
| 193     | Door Rear Right // Painting                         | Y          |
| 205     | Rocker Panel Right // Polish                        | Y          |
| 213     | Door Front Right // Painting                        | N          |
| 234     | Wing Front right // Repair & Painting               | Y          |
| 294     | Rear Loading Door Left // Repair & Painting         | Y          |
| 304     | Rear Loading Door Right // Repair & Painting        | Y          |
| 313     | Wheel Steel Front Left // Replace                   | N          |
| 323     | Wheel Steel Rear Left // Replace                    | N          |
| 411     | Seat Front Left // Repair                           | N          |
| 421     | Seat Front Right // Repair                          | N          |
| 433     | Seat Rear Left / Rear Coating / Replace             | Y          |
| 532     | Trunk Compartment / Side Cover Left / Replace       | N          |
| 533     | Trunk Compartment / Side Cover Right / Replace      | Y          |
| 540     | Interior // Repair 1                                | Y          |

|     |                                                              |   |
|-----|--------------------------------------------------------------|---|
| 541 | Interior // Repair 2                                         | Y |
| 543 | Interior // Ionization Odor                                  | N |
| 619 | Front Left Door Interior Coating / Control Module / Replace  | Y |
| 629 | Front Right Door Interior Coating / Control Module / Replace | N |
| 860 | Interior Cleaning // Small                                   | Y |

Damage Pictures



Roof // Polish-scratch



Door Rear Right // Painting-scratch




Rocker Panel Right // Polish-scratch



Door Front Right // Painting-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Front Right Door Interior Coating / Control Module / Replace-cracked



Seat Front Left // Repair-Incinerated



Seat Front Right // Repair-Incinerated



Trunk Compartment / Side Cover Left / Replace-missing



Front Bonnet // Polish-Chemical reaction





Interior Cleaning // Small-stain



Seat Rear Left / Rear Coating / Replace-worn



Front Left Door Interior Coating / Control Module / Replace-bad position



Headlight / Front left / Replace-scratch



Windshield // Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Door Rear Left / Window / Replace-scratch




Door Rear Left // Polish-scratch




Wheel Steel Rear Left // Replace-dent



Wheel Steel Front Left // Replace-dent




Wing Front right // Repair & Painting-dent



Wing Rear Right // Repair & Painting-dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Interior // Repair 2-scratch + dent



Interior // Repair 1-scratch + dent



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front // Painting-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Light / Rear left / Replace-scratch