

INSPECTION REPORT



End of contract

GENERAL INFO

File	319973
License plate	2AUN225
Vehicle identification number	VF3LCYHZKMS180416
Dossier	2021040006
Make	Peugeot 308 SW 1.5BHDi 130 Ac.
Mileage	125121
First registration	23/07/2021
client availability date	10/08/2026
inspectionDate	26/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
83	Door Front Left // Painting	N
87	Door Front Left / Trim / Replace	N
106	Door Rear Left // Polish	Y
110	Wing Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
203	Rocker Panel Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
274	Bumper Front / Grid Central / Replace	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Front // Painting-scratch




Wheel Alloy Front Left // Repair-scratch



Door Front Left // Painting-scratch



Door Rear Left // Polish-scratch



Bumper Rear // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Rocker Panel Right // Repair & Painting-scratch




Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch




Door Front Right // Smart Repair Small-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Front Left / Trim / Replace-scratch



Wing Rear Left // Smart Repair Small-dent



Trunk Compartment / Boot Cover / Replace-dent



Interior // Repair 1-Incinerated



Interior // Repair 2-Incinerated



Front Bonnet // Polish-Chemical reaction





Interior Cleaning // Small-stain



Bumper Front / Grid Central / Replace-bad position