

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 321775                        |
| License plate                 | 2AXN296                       |
| Vehicle identification number | YV1ZWBFVDN1473638             |
| Dossier                       | 2021 056 126                  |
| Make                          | Volvo V60 T6 PHEV Inscription |
| Mileage                       | 155199                        |
| First registration            | 30/08/2021                    |
| client availability date      | 14/09/2026                    |
| inspectionDate                | 21/09/2026                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | Y       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                           | Acceptable |
|---------|------------------------------------------------|------------|
| 13      | Bumper Front // Painting                       | N          |
| 32      | Front Bonnet // Painting                       | Y          |
| 66      | Wing Front Left // Polish                      | Y          |
| 72      | Side View Mirror Left // Painting              | Y          |
| 84      | Door Front Left // Repair & Painting           | Y          |
| 101     | Door Rear Left // Smart Repair Medium          | Y          |
| 104     | Door Rear Left // Repair & Painting            | N          |
| 114     | Wing Rear Left // Repair & Painting            | Y          |
| 134     | Bumper Rear // Repair & Painting               | N          |
| 150     | Rear Bonnet // Smart Repair Small              | N          |
| 169     | Rear Bonnet / Spoiler / Replace & Painting     | Y          |
| 194     | Door Rear Right // Repair & Painting           | Y          |
| 210     | Door Front Right // Smart Repair Small         | Y          |
| 216     | Door Front Right // Polish                     | Y          |
| 222     | Side View Mirror Right // Painting             | N          |
| 233     | Wing Front right // Painting                   | Y          |
| 310     | Wheel Two Tone Front Left // Repair            | N          |
| 320     | Wheel Two Tone Rear Left // Repair             | N          |
| 532     | Trunk Compartment / Side Cover Left / Replace  | Y          |
| 533     | Trunk Compartment / Side Cover Right / Replace | Y          |
| 549     | Interior / Headliner/ Replace                  | Y          |

## Damage Pictures



Side View Mirror Right // Painting-scratch




Wing Front right // Painting-scratch



Door Front Right // Polish-scratch




Door Front Right // Smart Repair Small-scratch




Rear Bonnet / Spoiler / Replace & Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Bumper Front // Painting-scratch



Front Bonnet // Painting-scratch



Door Rear Left // Smart Repair Medium-scratch



Rear Bonnet // Smart Repair Small-dent



Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Trunk Compartment / Side Cover Right / Replace-bad position



Trunk Compartment / Side Cover Left / Replace-bad position



Interior / Headliner/ Replace-bad position