

INSPECTION REPORT

End of contract

GENERAL INFO

File	319831
License plate	2DBP924
Vehicle identification number	VF3MJEHZUNS171217
Dossier	2022 117 197
Make	Peugeot 5008 2.0BHDi 132KW GT
Mileage	65340
First registration	26/01/2023
client availability date	10/08/2026
inspectionDate	26/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
132	Bumper Rear // Smart Repair Large	N
174	Light / Rear Right / Replace	N
180	Wing Rear Right // Smart Repair Small	N
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
153	Rear Bonnet // Painting	Y
157	Rear Bonnet / Trim / Replace	Y
225	Side View Mirror Right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N

Damage Pictures



Rear Bonnet // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Wing Front Left // Painting-scratch



Rear Bonnet / Trim / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Windshield // Repair-glass damage



Side View Mirror Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Tyre Rear Right // Replace-tear



Tyre Front Right // Replace-tear



Wheel Two Tone Front Right // Repair-scratch



Light / Rear Right / Replace-scratch



Wing Rear Right // Smart Repair Small-scratch



Bumper Rear // Smart Repair Large-scratch