

INSPECTION REPORT


End of contract

GENERAL INFO

File	318068
License plate	2ARG965
Vehicle identification number	VF3MCYHZUMS151006
Dossier	2021 078 050
Make	Peugeot 5008 1.5BHDi 96kW Allu
Mileage	181941
First registration	21/06/2021
client availability date	19/08/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
111	Wing Rear Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
35	Front Bonnet // Polish	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
139	Bumper Rear / Spoiler / Replace	N
147	Back Side / Whiper Arm / Replace	N
257	Front / Towing Cover / Replace	Y
282	Bumper Rear / Trim Center / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	Y
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures



Bumper Rear / Spoiler / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Front Bonnet // Polish-scratch



Front / Towing Cover / Replace-scratch




Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Rear / Trim Center / Replace-scratch + dent



Back Side / Whipper Arm / Replace-missing



Central Console / Cover Armrest / Replace Cover
Armrest-tear



Seat Front Left / Rear Coating / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Left / Trim / Replace-scratch



Wing Rear Left // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch