

INSPECTION REPORT


End of contract

GENERAL INFO

File	309010
License plate	1WWS594
Vehicle identification number	YV1XZACVDL2241254
Dossier	2019 071 051
Make	Volvo XC40 T4 Momentum Pro Gtr
Mileage	160571
First registration	09/10/2019
client availability date	30/03/2026
inspectionDate	07/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
234	Wing Front right // Repair & Painting	N
244	Light / Front Right / Replace	N
18	Bumper Front / Spoiler / Replace	N
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	Y
213	Door Front Right // Painting	N
218	Door Front Right / Door Handle / Replace	Y
341	Wheel Alloy Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N

Damage Pictures



Damage within Renta-norm-



Door Rear Left // Repair & Painting-scratch + dent




Front Bonnet / Insulation / Replace-cracked



Trunk Compartment / Side Cover Right / Replace-cracked




Rear Left Door Interior Coating // Repair-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Door Front Right // Painting-scratch



Door Front Right / Door Handle / Replace-scratch




Bumper Rear // Painting-scratch



Rear Right Door Interior Coating // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Windshield // Repair-glass damage



Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-cracked



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Light / Front Right / Replace-scratch



Wing Front right // Repair & Painting-scratch + dent