

INSPECTION REPORT

End of contract

GENERAL INFO

File	319621
License plate	2AWW932
Vehicle identification number	VR3EFYHWC MJ747636
Dossier	2021048076
Make	Peugeot Part.1.5BHDi 75 L1 L P
Mileage	104527
First registration	20/08/2021
client availability date	05/08/2026
inspectionDate	17/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
35	Front Bonnet // Polish	N
244	Light / Front Right / Replace	N
203	Rocker Panel Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
891	Lettering Removal 15min	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	N
88	Door Front Left / Door Handle / Replace	N
114	Wing Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
147	Back Side / Whiper Arm / Replace	N
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
198	Door Rear Right / Door Handle / Replace	N
218	Door Front Right / Door Handle / Replace	N
258	Towing Cover Rear // Replace	N
281	Bumper Rear / Trim Left / Replace	N
283	Bumper Rear / Trim Right / Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	N
422	Seat Front Right / Bottom Coating / Replace	N
427	Seat Front Right / Headrest / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
534	Trunk Compartment / Carpet / Replace	N

540	Interior // Repair 1	N
541	Interior // Repair 2	N
551	Central Console // Repair	N
561	Dashboard // Repair	N
564	Dashboard // Replace Completely	Y
568	Dashboard / Ventilation Outlet / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N
595	Trunk Lid Interior Coating / MDF Side Door Left / Replace	N
598	Trunk Lid Interior Coating / Handle / Replace	N
599	Trunk Lid Interior Coating / MDF Side Door Right / Replace	N
614	Front Left Door Interior Coating // Replace Completely	N
618	Front Left Door Interior Coating / Door Handle / Replace	N
619	Front Left Door Interior Coating / Control Module / Replace	N
624	Front Right Door Interior Coating // Replace Completely	N
628	Front Right Door Interior Coating / Door Handle / Replace	N
629	Front Right Door Interior Coating / Control Module / Replace	N
772	Interior / A Pillar Upper Cover / Replace	N
773	Interior / A Pillar Lower Cover / Replace	N
840	Interior Cleaning // Large	N

Damage Pictures



Light / Rear Right / Replace-scratch



Wing Rear Right // Polish-scratch



Dashboard / Ventilation Outlet / Replace-scratch




Wing Rear Left // Repair & Painting-scratch + dent




Door Front Left // Repair & Painting-scratch + dent



Door Front Left / Trim / Replace-stain



Wing Rear Left / Trim / Replace-stain



Door Rear Right // Painting-stain



Door Rear Right / Door Handle / Replace-stain



Door Front Right / Door Handle / Replace-stain



Trunk Compartment / Carpet / Replace-stain




Interior // Repair 1-stain



Trunk Compartment / Side Cover Left / Replace-stain



Trunk Compartment / Side Cover Right / Replace-stain



Trunk Lid Interior Coating / MDF Side Door Right /
Replace-stain



Trunk Lid Interior Coating / MDF Side Door Left /
Replace-stain



Trunk Lid Interior Coating / MDF Rear Left / Replace-stain



Trunk Lid Interior Coating / MDF Rear Right / Replace-stain



Towing Cover Rear // Replace-stain



Bumper Rear / Lower Cover Not Painted / Replace-stain



Bumper Rear / Trim Left / Replace-stain



Bumper Rear / Trim Right / Replace-stain



Back Side / Whipper Arm / Replace-stain



Trunk Lid Interior Coating / Handle / Replace-stain



Interior / A Pillar Upper Cover / Replace-stain



Front Right Door Interior Coating / Door Handle / Replace-stain



Front Right Door Interior Coating / Control Module / Replace-stain



Front Left Door Interior Coating / Control Module / Replace-stain



Front Left Door Interior Coating / Door Handle / Replace-stain



Front Left Door Interior Coating // Replace Completely-stain



Dashboard / Steering Wheel / Replace-stain




Interior / A Pillar Lower Cover / Replace-stain




Seat Front Left / Rear Coating / Replace-stain



Seat Front Left / Bottom Coating / Replace-stain




Front Right Door Interior Coating // Replace Completely-stain




Dashboard // Repair-stain



Central Console // Repair-stain



Seat Front Right / Headrest / Replace-stain



Interior Cleaning // Large-stain




Seat Front Right / Bottom Coating / Replace-stain



Bumper Front / Lower Cover Not Painted / Replace-stain



Door Front Left / Door Handle / Replace-stain



Dashboard // Replace Completely-hole



Interior // Repair 2-hole



Front Bonnet // Polish-scratch



Bumper Front / Spoiler / Replace-scratch



Light / Front Right / Replace-scratch



Lettering Removal 15min-



Rocker Panel Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent