

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306600
License plate	2ABL622
Vehicle identification number	W0VZCYHZ7M6806510
Dossier	2020 282 009
Make	Opel Grandland X 1.5D 96kW Edi
Mileage	110444
First registration	05/02/2021
client availability date	24/02/2026
inspectionDate	05/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
654	Lettering Removal 15min	N
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	N
162	Roof // Painting	N
860	Interior Cleaning // Small	N

## Damage Pictures




Damage within Renta-norm-scratch



Door Front Left // Painting-scratch



Wing Front Left // Painting-scratch



Roof // Painting-Chemical reaction



Interior Cleaning // Small-stain



Lettering Removal 15min-Remainder stickers