

INSPECTION REPORT



End of contract


GENERAL INFO

File	315706
License plate	JV5934
Vehicle identification number	VR3USHNSSNJ662349
Dossier	2021342028
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	50918
First registration	28/07/2022
client availability date	18/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	N
32	Front Bonnet // Painting	Y
63	Wing Front Left // Painting	Y
67	Wing Front Left / Trim / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	Y
193	Door Rear Right // Painting	N
282	Bumper Rear / Trim Center / Replace	N
562	Dashboard / Instruments Panel / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Right // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch






Bumper Rear / Trim Center / Replace-scratch



Wing Front Left / Trim / Replace-scratch



Wing Front Left // Painting-scratch






Front Bonnet // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Dashboard / Instruments Panel / Replace-scratch



Roof // Smart Repair Medium-dent



Interior Cleaning // Small-stain