

INSPECTION REPORT

End of contract

GENERAL INFO

File	321186
License plate	PW6623
Vehicle identification number	TMAJE811BMJ095730
Dossier	2021298018
Make	Hyundai TUCSON T-GDI hyb 180 S
Mileage	131096
First registration	19/05/2022
client availability date	31/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
104	Door Rear Left // Repair & Painting	N
107	Door Rear Left / Trim / Replace	N
13	Bumper Front // Painting	Y
28	Front / Calendar / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
213	Door Front Right // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
281	Bumper Rear / Trim Left / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
72	Side View Mirror Left // Painting	N
77	Side View Mirror Left / Shell / Replace Not Painted	N
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
110	Wing Rear Left // Smart Repair Small	Y
139	Bumper Rear / Spoiler / Replace	Y
150	Rear Bonnet // Smart Repair Small	N
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	N
236	Wing Front right // Polish	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
551	Central Console // Repair	N
553	Central Console / Gear Lever / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
614	Front Left Door Interior Coating // Replace Completely	N
634	Rear Left Door Interior Coating // Replace Completely	N

Damage Pictures



Front Left Door Interior Coating // Replace Completely-hole



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Side View Mirror Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent






Door Front Left // Painting-bad repair



Bumper Front / Trim Right / Replace-bad repair



Central Console / Gear Lever / Replace-Chemical reaction



Key Price Range 2 //-worn



Bumper Rear / Spoiler / Replace-scratch



Central Console // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Rear Left // Smart Repair Small-dent



Rear Bonnet // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Door Rear Left / Trim / Replace-scratch



Door Rear Left // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch





Bumper Rear / Trim Left / Replace-scratch + dent



Bumper Front // Painting-scratch



Front / Calendar / Replace-stone chipping



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Painting-scratch



Door Rear Right / Trim / Replace-scratch