

INSPECTION REPORT


End of contract

GENERAL INFO

File	314034
License plate	JV5911
Vehicle identification number	VR3USHNSSNJ662331
Dossier	2021342104
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	41592
First registration	26/07/2022
client availability date	29/05/2026
inspectionDate	02/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
274	Bumper Front / Grid Central / Replace	N
32	Front Bonnet // Painting	N
63	Wing Front Left // Painting	N
233	Wing Front right // Painting	N
38	Front Bonnet / Insulation / Replace	N
67	Wing Front Left / Trim / Replace	N
84	Door Front Left // Repair & Painting	Y
135	Bumper Rear // Replace & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
175	Light / Rear Right On Rear Bonnet / Replace	N
187	Wing Rear Right / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
237	Wing Front right / Trim / Replace	Y
258	Towing Cover Rear // Replace	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Towing Cover Rear // Replace-scratch



Wing Front Left / Trim / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Wing Rear Right / Trim / Replace-scratch




Door Rear Right / Trim / Replace-scratch



Wing Front right / Trim / Replace-scratch



Bumper Rear // Replace & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rear Bonnet // Polish-Chemical reaction



Roof // Polish-Chemical reaction



Front Bonnet / Insulation / Replace-tear



Bumper Front // Painting-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front / Grid Central / Replace-scratch



Bumper Front / Spoiler / Replace-scratch + dent





Front Bonnet // Painting-scratch



Wing Front Left // Painting-scratch



Wing Front right // Painting-scratch