

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307685
License plate	2ADT820
Vehicle identification number	W1K1183861N201022
Dossier	2020274082
Make	Mercedes CLA 250 e Bus.Solut.A
Mileage	82107
First registration	03/03/2021
client availability date	13/03/2026
inspectionDate	18/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES


Damages	Type	Acceptable
135	Bumper Rear // Replace & Painting	N
154	Rear Bonnet // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	N
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
41	Windshield // Replace	Y
100	Door Rear Left // Smart Repair Small	N
161	Roof // Smart Repair Medium	N
330	Wheel Two Tone Rear Right // Repair	N

## Damage Pictures



Damage within Renta-norm-scratch





Windshield // Replace-glass damage



Wheel Two Tone Rear Right // Repair-scratch



Roof // Smart Repair Medium-dent



Door Rear Left // Smart Repair Small-dent



Bumper Rear // Replace & Painting-scratch + dent



Bumper Rear / Trim Center / Replace-cracked



Rear Bonnet // Repair & Painting-dent



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-cracked