

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	310990
License plate	2AGS804
Vehicle identification number	W0VEUHNP2MJ621045
Dossier	2020303089
Make	Opel Comb.1.2 81kW 2.0T L1H1 E
Mileage	8386
First registration	29/03/2021
client availability date	22/04/2026
inspectionDate	04/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
38	Front Bonnet / Insulation / Replace	N
81	Door Front Left // Smart Repair Medium	N
114	Wing Rear Left // Repair & Painting	Y
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
624	Front Right Door Interior Coating // Replace Completely	Y
883	Key Price Range 2 //	N


## Damage Pictures




Bumper Front // Painting-scratch



Door Rear Right // Polish-scratch




Front Right Door Interior Coating // Replace Completely-scratch




Door Front Left // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Wing Rear Left // Repair & Painting-dent



Front Bonnet / Insulation / Replace-hole