

INSPECTION REPORT



End of contract


GENERAL INFO

File	313869
License plate	2EXR022
Vehicle identification number	VF3VFEHS7R7802372
Dossier	2023088280
Make	Peugeot Expert 2.0BHDi 145 Sta
Mileage	18748
First registration	29/02/2024
client availability date	28/05/2026
inspectionDate	04/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
41	Windshield // Replace	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
87	Door Front Left / Trim / Replace	Y
117	Wing Rear Left / Trim / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y
294	Rear Loading Door Left // Repair & Painting	Y
302	Rear Loading Door Right / Smart Repair Large	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
549	Interior / Headliner/ Replace	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Interior / Headliner/ Replace-Incinerated




Trunk Compartment / Side Cover Right / Replace-scratch



Rear Loading Door Right / Smart Repair Large-scratch



Trunk Lid Interior Coating / MDF Rear Left / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Door Front Left / Trim / Replace-scratch




Side View Mirror Left / Shell / Replace Not Painted-scratch




Windshield // Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch