

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306813
License plate	1XJR957
Vehicle identification number	W1V4156031U280413
Dossier	2019331162
Make	Mercedes Citan 109CDI L2 Perf.
Mileage	107787
First registration	17/01/2020
client availability date	27/02/2026
inspectionDate	10/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES


Damages	Type	Acceptable
32	Front Bonnet // Painting	N
40	Windshield // Repair	Y
163	Roof // Repair & Painting	N
294	Rear Loading Door Left // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
316	Tyre Front Left // Replace	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
599	Trunk Lid Interior Coating / MDF Side Door Right / Replace	N
883	Key Price Range 2 //	N

## Damage Pictures





Damage within Renta-norm-scratch



Roof // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent





Rear Loading Door Right // Repair & Painting-scratch + dent





Trunk Lid Interior Coating / MDF Side Door Right / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked



Windshield // Repair-glass damage





Front Bonnet // Painting-Chemical reaction



Tyre Front Left // Replace-tear