

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	309002
License plate	2FSC320
Vehicle identification number	VR3FRHNS4RY549058
Dossier	2023356428
Make	Peugeot 308 SW 1.2 130 Active
Mileage	19188
First registration	31/07/2024
client availability date	25/03/2026
inspectionDate	26/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
93	Rocker Panel Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
134	Bumper Rear // Repair & Painting	N
81	Door Front Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
321	Wheel Alloy Rear Left // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures



Wheel Alloy Rear Left // Repair-bad repair



Interior Cleaning // Small-stain



Door Rear Left // Repair & Painting-scratch + dent



Door Front Left // Smart Repair Medium-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Repair & Painting-dent



Rocker Panel Left // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent