

INSPECTION REPORT



End of contract

GENERAL INFO

File	321825
License plate	2CHG195
Vehicle identification number	VR3FCYHZTNY582952
Dossier	2021280110
Make	Peugeot 308 SW 1.5BHDi 130 GT
Mileage	144429
First registration	27/07/2022
client availability date	10/09/2026
inspectionDate	16/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
81	Door Front Left // Smart Repair Medium	N
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
139	Bumper Rear / Spoiler / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
183	Wing Rear Right // Painting	Y
190	Door Rear Right // Smart Repair Small	N
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wing Rear Left // Painting-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch



Wing Rear Right // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Smart Repair Small-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Rear / Spoiler / Replace-cracked



Front Bonnet / Insulation / Replace-tear