

INSPECTION REPORT

End of contract

GENERAL INFO

File	318926
License plate	2DVR286
Vehicle identification number	VR3UBYHTKP5062806
Dossier	2022 363 370
Make	Peugeot 208 1.5BHDi 100 Active
Mileage	68865
First registration	06/07/2023
client availability date	28/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	Y
39	Engine Compartment / Silencer / Replace	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	Y
157	Rear Bonnet / Trim / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
183	Wing Rear Right // Painting	Y
194	Door Rear Right // Repair & Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	Y
336	Tyre Rear Right // Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
540	Interior // Repair 1	Y
614	Front Left Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	Y
883	Key Price Range 2 //	Y

Damage Pictures



Rear Bonnet / Trim / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Wheel Front Right / Wheel Cover / Replace-scratch




Wheel Front Left / Wheel Cover / Replace-scratch





Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch





Wheel Rear Left / Wheel Cover / Replace-scratch



Wing Rear Right // Painting-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Door Rear Right // Repair & Painting-dent



Bumper Rear // Repair & Painting-scratch + dent




Engine Compartment / Silencer / Replace-cracked



Interior // Repair 1-missing



Front Bonnet / Insulation / Replace-tear



Tyre Rear Right // Replace-tear



Interior Cleaning // Small-stain