

INSPECTION REPORT


End of contract

GENERAL INFO

File	321283
License plate	PR9759
Vehicle identification number	VSSZZZKJ0PR040350
Dossier	2022336004
Make	Seat Arona TSI 110 Style
Mileage	202213
First registration	09/01/2023
client availability date	01/09/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
540	Interior // Repair 1	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
551	Central Console // Repair	N
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch



Wing Rear Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Bumper Front // Polish-scratch





Door Front Left // Smart Repair Small-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior // Repair 1-scratch



Interior // Repair 1-Incinerated





Central Console // Repair-scratch



Dashboard // Repair-scratch




Rocker Panel Right // Smart Repair Medium-dent



Door Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-glass damage



Interior Cleaning // Small-stain