

INSPECTION REPORT

End of contract

GENERAL INFO

File	318216
License plate	2CBY644
Vehicle identification number	KMHC851CGNU287848
Dossier	2021319101
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	127041
First registration	30/05/2022
client availability date	15/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
891	Lettering Removal 15min	N
136	Bumper Rear // Polish	Y
154	Rear Bonnet // Repair & Painting	N
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	N
311	Wheel Alloy Front Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Polish-scratch



Roof // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Seat Front Right // Repair-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior // Repair 1-scratch



Seat Front Left // Repair-scratch



Wing Rear Right // Smart Repair Small-dent



Rear Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Lettering Removal 15min-