

INSPECTION REPORT






End Of Contract

GENERAL INFO

File	286691
License plate	1YNQ848
Vehicle identification number	WAUZZZFYXL2111479
Dossier	2020002154
Make	Audi Q5 30 TDi 100kW Bus.Ed.Sp
Mileage	143697.00
First registration	13/10/2020
	25/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
64	Wing Front Left // Repair & Painting	N
67	Wing Front Left / Trim / Replace	N
221	Side View Mirror Right // Plastic Repair	N
222	Side View Mirror Right // Painting	N
71	Side View Mirror Left // Plastic Repair	N
83	Door Front Left // Painting	N
101	Door Rear Left // Smart Repair Medium	N
133	Bumper Rear // Painting	N
181	Wing Rear Right // Smart Repair Medium	N
191	Door Rear Right // Smart Repair Medium	N
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch






Bumper Rear // Painting-scratch



Seat Front Left // Repair-scratch



Seat Front Right // Repair-scratch



Door Front Left // Painting-scratch



Side View Mirror Left // Plastic Repair-scratch



Door Rear Right // Smart Repair Medium-scratch + dent



Wing Rear Right // Smart Repair Medium-scratch + dent



Door Rear Left // Smart Repair Medium-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Wing Front Left / Trim / Replace-scratch



Bumper Front // Painting-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right // Plastic Repair-scratch