

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	312740
License plate	2BNB005
Vehicle identification number	VR3USHNKNJ536431
Dossier	2021300141
Make	Peugeot 2008 1.2 74kW Allure
Mileage	20893
First registration	20/01/2022
client availability date	01/06/2026
inspectionDate	08/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
80	Door Front Left // Smart Repair Small	Y
107	Door Rear Left / Trim / Replace	Y
136	Bumper Rear // Polish	Y
153	Rear Bonnet // Painting	Y
193	Door Rear Right // Painting	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	N
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
641	Rear Right Door Interior Coating // Repair	N

## Damage Pictures



Rear Bonnet // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Painting-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Front Bonnet // Polish-scratch



Door Rear Right // Painting-scratch




Side View Mirror Right // Painting-scratch



Bumper Rear // Polish-scratch



Door Front Right // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-missing



Door Rear Left / Trim / Replace-tear