

INSPECTION REPORT

End of contract

GENERAL INFO

File	309069
License plate	2FSC380
Vehicle identification number	VR3FRHNS3RY549066
Dossier	2023356408
Make	Peugeot 308 SW 1.2 130 Active
Mileage	3832
First registration	31/07/2024
client availability date	26/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
562	Dashboard / Instruments Panel / Replace	Y

Damage Pictures



Door Front Left // Smart Repair Small-scratch



Dashboard / Instruments Panel / Replace-N comf / out of order