

INSPECTION REPORT


End of contract

GENERAL INFO

File	321091
License plate	QF9845
Vehicle identification number	VR3FPHNSTPY624790
Dossier	2023097003
Make	Peugeot 308 1.2PT 131 GT A
Mileage	69820
First registration	28/11/2023
client availability date	28/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
35	Front Bonnet // Polish	Y
54	Headlight / Front left / Replace	N
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
165	Roof // Polish	Y
194	Door Rear Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	Y
216	Door Front Right // Polish	Y
271	Bumper Front / Trim Left / Replace	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
316	Tyre Front Left // Replace	N
320	Wheel Two Tone Rear Left // Repair	N
326	Tyre Rear Left // Replace	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Repair & Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Door Front Right // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left // Repair & Painting-dent



Rear Bonnet // Smart Repair Small-dent




Door Rear Right // Repair & Painting-scratch + dent



Headlight / Front left / Replace-cracked



Front Bonnet // Polish-Chemical reaction



Roof // Polish-Chemical reaction



Tyre Front Left // Replace-tear



Tyre Front Right // Replace-tear



Tyre Rear Left // Replace-tear