

INSPECTION REPORT




End Of Contract

GENERAL INFO

File	286120
License plate	2AAR266
Vehicle identification number	TMBJJ7NX0MY107928
Dossier	2020328079
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	149509.00
First registration	02/02/2021
	20/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	Y
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	N
180	Wing Rear Right // Smart Repair Small	N
196	Door Rear Right // Polish	Y
236	Wing Front right // Polish	Y
274	Bumper Front / Grid Central / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Rear Right // Polish-scratch



Wing Front right // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Smart Repair Medium-dent




Bumper Front // Repair & Painting-dent



Wing Rear Right // Smart Repair Small-dent



Bumper Rear // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-cracked



Windshield // Replace-cracked