

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306117
License plate	1XHN656
Vehicle identification number	YV1XZ72VDL2278101
Dossier	2019343007
Make	Volvo XC40 D3 Momentum Pro Gtr
Mileage	223485
First registration	08/01/2020
client availability date	17/02/2026
inspectionDate	20/02/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
234	Wing Front right // Repair & Painting	N
237	Wing Front right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
41	Windshield // Replace	N
80	Door Front Left // Smart Repair Small	N
101	Door Rear Left // Smart Repair Medium	N
124	Light / Rear left / Replace	N
155	Rear Bonnet // Replace & Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
174	Light / Rear Right / Replace	N
180	Wing Rear Right // Smart Repair Small	N
199	Door Rear Right / Window / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
258	Towing Cover Rear // Replace	N
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
346	Tyre Front Right // Replace	N
535	Trunk Compartment / Window Shelf / Replace	N
543	Interior // Ionization Odor	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N
850	Certificate of Conformity //	N
881	Key Price Range 1 //	N

## Damage Pictures



Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Right / Window / Replace-scratch



Wing Rear Right // Smart Repair Small-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Windshield // Replace-cracked



Towing Cover Rear // Replace-missing



Trunk Compartment / Window Shelf / Replace-missing





Interior Cleaning // Large-dirty



Tyre Front Right // Replace-tear



Dashboard / Steering Wheel / Replace-worn



Rear Bonnet // Replace & Painting-bad position



Door Front Left // Smart Repair Small-dent



Door Rear Left // Smart Repair Medium-scratch + dent






Wing Front right // Repair & Painting-scratch + dent




Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch





Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch