

INSPECTION REPORT



End of contract


GENERAL INFO

File	307810
License plate	2AGK571
Vehicle identification number	VF3MICYHZMMS069987
Dossier	2020282024
Make	Peugeot 3008 1.5BHdi 96kW GT
Mileage	55425
First registration	25/03/2021
client availability date	11/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES


Damages	Type	Acceptable
183	Wing Rear Right // Painting	N
187	Wing Rear Right / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
106	Door Rear Left // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures





Damage within Renta-norm-scratch



Wheel Two Tone Rear Right // Repair-scratch



Trunk Compartment / Boot Cover / Replace-missing



Interior // Repair 1-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Front Bonnet // Polish-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wing Rear Right / Trim / Replace-scratch



Wing Rear Right // Painting-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch