

INSPECTION REPORT

End of contract

GENERAL INFO

File	312904
License plate	2CAJ866
Vehicle identification number	NMTK33BXX0R164556
Dossier	2022 111 028
Make	Toyota C-HR 1.8 Hybrid C-Lub M
Mileage	90660
First registration	10/05/2022
client availability date	21/05/2026
inspectionDate	03/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Door Rear Left // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Smart Repair Medium-dent



Side View Mirror Right / Direction Indicator / Replace-cracked