

INSPECTION REPORT


End of contract

GENERAL INFO

File	315009
License plate	XY4768
Vehicle identification number	VR3USHNSSNJ662303
Dossier	2021342037
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	59647
First registration	28/07/2022
client availability date	10/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	N
272	Bumper Front / Trim Right / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
187	Wing Rear Right / Trim / Replace	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
38	Front Bonnet / Insulation / Replace	N
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	N
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
214	Door Front Right // Repair & Painting	Y
282	Bumper Rear / Trim Center / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Right // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Rocker Panel Left // Smart Repair Medium-dent



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear / Trim Center / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front / Trim Right / Replace-scratch





Wing Rear Right / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent