

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307493
License plate	1YGK059
Vehicle identification number	TMBJB7NS2M8007380
Dossier	2020132007
Make	Skoda Kod.1.5TSI 110kW Style
Mileage	123052
First registration	24/08/2020
client availability date	09/03/2026
inspectionDate	13/03/2026



## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



## DAMAGES

Damages	Type	Acceptable
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures





Damage within Renta-norm-scratch



Seat Rear Left // Repair-scratch



Roof // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch