

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	310659
License plate	EB7699
Vehicle identification number	VSSZZZKJ3RR059252
Dossier	2023215015
Make	Seat Ibiza 1.0eTSi 110 Xcellen
Mileage	66153
First registration	02/02/2024
client availability date	15/04/2026
inspectionDate	17/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
271	Bumper Front / Trim Left / Replace	N
40	Windshield // Repair	Y
61	Wing Front Left // Smart Repair Medium	N
81	Door Front Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
225	Side View Mirror Right // Polish	Y
316	Tyre Front Left // Replace	Y
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y


## Damage Pictures



Roof // Polish-Chemical reaction



Tyre Front Left // Replace-worn



Windshield // Repair-cracked



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Medium-scratch




Side View Mirror Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Painting-scratch



Wing Front Left // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Trim Left / Replace-cracked