

INSPECTION REPORT



End of contract

GENERAL INFO

File	319162
License plate	2ARV447
Vehicle identification number	W0V7D9ED7M4208044
Dossier	2021088120
Make	Opel Opel Crossland 1.2 81kW E
Mileage	68304
First registration	17/03/2021
client availability date	10/08/2026
inspectionDate	14/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
107	Door Rear Left / Trim / Replace	N
110	Wing Rear Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
180	Wing Rear Right // Smart Repair Small	N
190	Door Rear Right // Smart Repair Small	Y
203	Rocker Panel Right // Repair & Painting	N
213	Door Front Right // Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
551	Central Console // Repair	N
561	Dashboard // Repair	N
566	Dashboard / Cover Storage Tray / Replace	N
569	Dashboard / Steering Wheel / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	N
773	Interior / A Pillar Lower Cover / Replace	N
883	Key Price Range 2 //	N

Damage Pictures




Rear Bonnet / Rear Window / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rear Bonnet // Painting-scratch



Door Rear Left // Painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Central Console // Repair-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Seat Front Right // Repair-scratch



Dashboard / Cover Storage Tray / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Door Rear Right // Smart Repair Small-scratch




Door Front Right // Painting-scratch



Wing Rear Right // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Dashboard // Repair-scratch + dent





Rocker Panel Right // Repair & Painting-scratch + dent



Door Rear Left // Smart Repair Medium-tear



Dashboard / Steering Wheel / Replace-worn