



ARVAL
BNP PARIBAS GROUP

CH9829

INSPECTION REPORT


End of contract

GENERAL INFO

File	319682
License plate	CH9829
Vehicle identification number	W0VZCYHZ6P6054058
Dossier	2023265004
Make	Opel Grandland 1.5TD 130 Bus.E
Mileage	198758
First registration	12/01/2024
client availability date	06/08/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	N
117	Wing Rear Left / Trim / Replace	N
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	Y
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	N
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
561	Dashboard // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N


Damage Pictures



Roof // Smart Repair Medium-scratch



Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Dashboard // Repair-scratch



Wing Rear Left / Trim / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch




Wing Front right / Trim / Replace-scratch




Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Rocker Panel Left // Smart Repair Medium-dent



Roof // Repair & Painting-scratch + dent



Door Rear Left // Painting-bad repair



Interior Cleaning // Small-dirty