

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	310144
License plate	2ADK610
Vehicle identification number	YV1UZBFVDM1822563
Dossier	2020349086
Make	Volvo XC60 T6 e4x4 Insc.Ex.PHE
Mileage	116563
First registration	01/03/2021
client availability date	16/04/2026
inspectionDate	27/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
14	Bumper Front // Repair & Painting	N
133	Bumper Rear // Painting	N
273	Bumper Front / Grid Left / Replace	Y
281	Bumper Rear / Trim Left / Replace	Y
320	Wheel Two Tone Rear Left // Repair	Y

## Damage Pictures



Damage within Renta-norm-




Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Grid Left / Replace-bad position



Bumper Rear / Trim Left / Replace-bad position



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Right // Painting-scratch



Door Front Right // Painting-scratch