



ARVAL
BNP PARIBAS GROUP

2CMW472

INSPECTION REPORT

End of contract

GENERAL INFO

File	322254
License plate	2CMW472
Vehicle identification number	VR3FRHNSTNY553853
Dossier	2022252074
Make	Peugeot 308 SW 1.2 130 Active
Mileage	58971
First registration	21/09/2022
client availability date	14/09/2026
inspectionDate	22/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
13	Bumper Front // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
110	Wing Rear Left // Smart Repair Small	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
181	Wing Rear Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
431	Seat Rear Left // Repair	N

Damage Pictures



Bumper Front // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Left // Smart Repair Small-dent



Wing Rear Right // Smart Repair Medium-scratch + dent




Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Seat Rear Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch