

INSPECTION REPORT

End of contract

GENERAL INFO

File	308625
License plate	2BLF048
Vehicle identification number	TMBER6NW3N3051784
Dossier	2021216001
Make	Skoda Scala 1.0TSI 81kW Monte
Mileage	172884
First registration	03/01/2022
client availability date	02/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
52	Headlight LED / Front left / Replace	N
183	Wing Rear Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Headlight LED / Front left / Replace-scratch



Bumper Front // Smart Repair Large-scratch




Wheel Two Tone Front Left // Repair-scratch



Wing Rear Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Windshield // Repair-glass damage



Front Bonnet // Painting-stone chipping