

INSPECTION REPORT



End of contract

GENERAL INFO

File	314186
License plate	2ALF360
Vehicle identification number	TMBJJ7NS7M8042547
Dossier	2021005049
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	139563
First registration	03/05/2021
client availability date	01/06/2026
inspectionDate	09/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
67	Wing Front Left / Trim / Replace	N
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
41	Windshield // Replace	Y
64	Wing Front Left // Repair & Painting	Y
86	Door Front Left // Polish	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
116	Wing Rear Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	Y
226	Side View Mirror Right / Shell / Replace Painted	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch




Windshield // Replace-scratch



Door Front Left / Trim / Replace-scratch




Door Front Left // Polish-scratch



Wing Rear Left // Polish-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard // Repair-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Left // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Side View Mirror Right / Shell / Replace Painted-cracked



Interior Cleaning // Small-stain




Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wing Front Left / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch



Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch